

FIG. 4




FIG. 5





FIG. 6

fast streeing mirror 2	setting ₀₄	setting ₁₄	setting ₂₄
fast streeing mirror 1	setting ₀₃	selfing ₁₃	setting ₂₃
deformable mirror 2	setting ₀₂	setting ₁₂	setting ₂₂
deformable mirror 1	setting ₀₁	setting ₁₁	setting ₂₁
setting measurement time (seconds)	0	. 5	10

FIG. 6A






FIG. 8




FIG. 10

